



Check us out on the web at
www.rectoday.net
 208-442-9350

Site: ABC School
 Playworld - Challenger

Date of Inspection: 1/1/2019
Inspection Completion Time: 4:00 - 4:15 pm

Inspector: Recreation Today
NPSI Certification#: 00000-1234

Attention Administrator:

A comprehensive inspection of your playground, play structures and use zones was completed by a certified playground safety inspector.

Actions Taken:

- Checked and tightened all bolts, checked all footings and use zones for equipment, checked safety surfacing levels for proper fall protection.

Actions Required:

- Engineered Wood Fiber (EWF) is 8" low and needs to be recapped. A total of 166 cu yds is needed to bring surfacing to a compliant level. Bottom of slide bedway to EWF should not exceed 11". Geo-cloth is exposed; there is trash in pod; and weeds are growing in pod. (See Image 4.)
- The ADA ramp is in good condition. To make ramp compliant, please rake EWF onto end of ramp which drops onto the playground surface.
- Missing bolts on slide and crawl tube.
- There are no Risk Management signs on the playground. It is a requirement per the CPSC Guidelines that proper signs be placed on the playground stating age appropriateness for the equipment and that the playground is not supervised (to be used at your own risk). Warning labels are present.

Items to Watch:

- Cracking in covering on platforms.
- Paint flaking on structure.

If you have any questions or require further assistance, please contact us at 208-442-9350. Thank you for allowing us to serve you.

Sincerely,

Recreation Today

Inspection Totals	
Action Taken	1
Corrective Action Needed	4
Watching	2

Detailed Inspection Report

Site: ABC School

4:00 - 4:15 pm

1/1/2019

Play structure #1

Structure Type:

Playworld - Challenger

Detailed List of Inspection

Inspected	Compliant?	Status of Part	Comments:
Structural Overview	Yes	Checked & Tightened	
Structural Overview (Posts)	Yes	Good Condition	
Structural Overview (Concrete Footings)	Yes	Good Condition	
Surfacing Overview	No	Needs to be Filled	EWF is 8 inchs low.
ADA Accessibility	No	Needs Repair	Rake EWF up to ramps.
Decks	Yes	Good Condition	
Pipefittings/Clamps	Yes	Good Condition	
All Bolts	No	Requires Replacement	Missing bolts on slide and crawl tube.
Barriers	Yes	Good Condition	
Climbers	Yes	Good Condition	
Climbing Walls	Yes	Good Condition	
Handrails	Yes	Good Condition	
Platforms	Yes	Watch List	Cracking in covering on platforms.
Signage	No	Requires Replacement	No signage, does have labels. Climber is over 32 inches; not for children under 5.
Slides	No	Needs Repair	See bolts.
Steps/Ladders	Yes	Good Condition	
Use Zones	Yes	Good Condition	

Additional Comments:

Watch: Paint flaking.

Image 1



Structure Overview:
Action taken at time of inspection:
This is a picture of the Playworld Systems structure. All bolts were checked and tightened.

Image 2



Structure Overview (Posts):
Action taken at time of inspection:
All posts were checked and all are in "good condition". All barriers, bridges, climbers, climbing walls, handrails, platforms, slides, steps and ladders were also checked and are in "good condition".



Image 3



Structure Overview (Concrete Footings):
Action taken at time of inspection:
All concrete footings have been checked and are solid and listed as "good condition".

Image 4



Surfacing Overview:
Corrective action needed:
Engineered Wood Fiber (EWF) is 8" low and needs to be recapped. A total of 166 cu yds is needed to bring surfacing to a compliant level. Bottom of slide bedway to EWF should not exceed 11". There is exposed geocloth and weeds growing in fall material.



Image 5



ADA Accessibility:

Corrective action needed:

The ADA ramp is in good condition. To make ramp compliant, please rake EWF onto end of ramp which drops onto the playground surface.

Image 6



Structure Recommendation*:

Corrective action needed:

Missing bolts on slide and crawl tube..



** Requirements are from CPSC Guidelines

* Recommendations are from Recreation Today

Image 7



Structure Recommendation*:

Watch:

Paint is flaking on structure.

Image 8



Structure Recommendation*:

Watch:

Cracking in covering on platforms.

Image 9



Signage Requirements:**
Corrective action needed:
There is no Risk Management sign on the playground. Warning labels are present. It is a requirement per the CPSC Guidelines that proper signs be placed on the playground. Sign

** Requirements are from CPSC Guidelines
* Recommendations are from Recreation Today